




Stepper motor **SM5776**

Driver: **SMD-4.2**

Voltage: 48VDC

Current: 2.8A



x axis - rotation speed, rpm;

y axis - torque, kgf*cm