




Stepper motor **SM8680** – serial connection

Driver: **SMD-9.0**

Microstepping: 1/2

Current: 4.2A



x axis - rotation speed, rpm;

y axis - torque,kgf*cm